GENERAL NOTES

- EXT'G CONDITIONS ARE BASED ON AVAILABLE INFORMATION. PRIOR TO SUBMITTING A BID, THE CONTRACTOR SHALL VISIT THE SITE TO VERIFY ALL CONDITIONS AND DIMENSIONS. NO EXTRAS WILL BE GIVEN FOR FAILURE TO INVESTIGATE.
- 2. MEANS AND METHODS ARE THE RESPONSIBILITY OF THE CONTRACTOR.
 INCLUDE FOR A COMPLETE INSTALLATION WITHOUT ADDITIONAL COST TO
 THE OWNER.
- 3. FIELD ORGANIZE AND INSTALL ALL EQUIPMENT, DUCTWORK, PIPING, CONDUIT, ETC FOR MAXIMUM CLEARANCE AND MAINTENANCE ACCESSIBILITY. (ALL TRADES)
- (ALL IRADES)

 4. EXISTING PIPING, DUCTWORK AND EQUIPMENT SHOWN LIGHT. NEW PIPING, DUCTWORK AND EQUIPMENT SHOWN BOLD.
- 5. EXISTING PIPING, DUCTWORK AND EQUIPMENT TO REMAIN OR THAT WHICH IS NOTED TO BE REUSED SHALL BE PROTECTED FROM DAMAGE.

KEY NOTES

- COMBINE CONDENSATE DRAINS IN THE ATTIC SPACE AND SLOPE ACCORDINGLY TO BRANCH TAIL PIECE OF FIXTURE AS SHOWN. PROTECT CONDENSATE LINES FROM FREEZING IN THE ATTIC WITH INSULATION.
- COMBINE NEW SANITARY VENTS ABOVE CEILING, ROUTE AND CONNECT TO EXISTING VENTING WITH VTR, CONNECT AS REQ'D..
- EXISTING VENTING WITH VTR, CONNECT AS REQ'D..

 3. COORDINATE ALL DRAIN CONNECTIONS REQ'D FOR THIS NEW KITCHEN EQUIPMENT. CONNECT PER MFGR'S INSTALLATION INSTRUCTIONS.
- 4. DISHWASHER TO DISCHARGE TO BRANCH TAIL PIECE UNDER THE SINK.

ENGINEERING
DESIGN ASSOCIATES

1607 CY AVE, STE 303 // CASPER, WY 82604
307-266-5033 // MAIL@EDAENGINEERING.COM

LD STONEY REMODEL HASE TWO 0 NORTH 4TH STREET

THESE DRAWINGS AND THE DESIGNS HERE ILLUSTRATED ARE THE SOLE
PROPERTY OF STATEMITHOOUT EXPRESS WRITTEN DESIGNS OF STATEMITHON TARCHITECTS AND MAY NOT BE REPRODUCED IN WHOLE OR IN PART WITHHOUT EXPRESS WRITTEN PERMISSION OF STATEMINE ON THE STATEMINE OF STATEMINE OF

PROJECT

DATE

DRAWN

SHEET
SECOND FLOOR
WASTE & VENT

IEET

5.20

SECOND FLOOR PLAN - WASTE & VENT

PLAN NORTH

1/4" = 1'-0" 01